

Submit Form To:

Amarillo Field Office
ATTN: Assistant Field Manager for Operations
801 S. Fillmore, Suite 500
Amarillo, TX 79101

Cliffside Gas Plant Status Report

Date & Time of Outage: October 15, 2016 at 0800 (CDT)

Cause of Outage: Scheduled outage for annual maintenance and repairs.

Factors Causing Restart:

- Scheduled outage.

Current Status:

- 1510 hours, Wednesday, October 26, 2016 – Plant is operating well. Producing 3550 Mscf/d of helium into the Helium Conservation Pipeline.

Forecast:

- Maintain production.

Pipeline Pressure at Cliffside: At 1510 (CDT), Wednesday, October 26, 2016 = 915 psig

Next Report: Final report following scheduled outage. Thank you.

Points of Contact:

Sam Burton, Acting Field Manager at 806-683-7726, sburton@blm.gov, or
Wesley W. Ingram, Acting AFM-HE Ops at 806-356-1023, wingram@blm.gov